CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Name of Work : Pot hole filling in Jalahalli surrounding areas of Bhovi Colony Khata nagara Sidhartha nagara Jalahalli colony in ward no 16 Jalahalli, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** R R Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**Sri. S Santhosh Kumar,** Contractor, Bangalore.
Total Cost	:	Rs. 15.00 Lakhs
Date of Inspection	:	26.02.2021
Status of Bill	:	1st and final Bill
In the Presence of	:	(a) **Assistant Engineer (W. No.16),** BBMP, Bangalore.
	:	(b) **Mr. Mohan G,** Engineer M/S Civil Quality Consultants and Engineers, Bangalore

Sl.No	Description of the Item		Quantity	Unit	Comments / observations
1	KSRRB 300-1. Earthwork excavation by manual means in hard soil involving an average horizontal throw upto 2 meters	:	367.35	Cum	Work done up to the billed quantity and Quality is satisfactory
2	Providing, laying , spreading and compacting graded stones aggregate to wet mix macadam specifications including pre	:	275.51	Cum	Work done up to the billed quantity and Quality is satisfactory
3	Filling potholes and patch Repairs with Bituminous Concrete, 40mm. Removal of all failed material, trimming of	:	1836.76	Sqm	Work done up to the billed quantity and Quality is satisfactory

for CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-560 056.
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner